



*Subsurface Site Investigation
Hadad Motors
Trinidad, Colorado
Page 5*

7.0 SUMMARY / CONCLUSIONS

Geologic Services & Consultants, Inc. was contracted by Mr. Joe Hadad of Hadad Motors to perform a Subsurface Site Investigation at the Hadad Motors facility in Trinidad, Colorado. Seven soil samples were obtained from the base of the UST cavity, product lines and dipenser area. Concentrations of petroleum contamination were not indicated in laboratory analyses of soil. Based upon available information, GSC concludes that significant petroleum contamination of soils is not present in the vicinity of the former UST systems at this site.



ANACHEM INC.

8 Prestige Circle, Suite 104 Allen, Texas 75002
972/727-9003 • FAX # 972/727-9686 • 1-800-966-1186

Customer Name: GSC, Inc. -Colorado
Date Received: July 1, 1997 at 10:00:00
Date Reported: July 2, 1997
Submission #: 9707000010
Project: HADAD MOTORS

SAMPLES The submission consisted of 7 samples with sample I.D.'s shown in the attached data tables.

TESTS The samples listed in the attached result pages were analyzed for:
* BTEX/TPH (MOD 8020/MOD 8015 GAS-RANGE COLORADO DL)

Distribution Of Reports

1-Mr. Mike Kunz of GSC, Inc. -Colorado
Ph. 719-579-8066 Fax 719-579-8028

Respectfully Submitted,
Anachem, Inc.


Howard H. Hayden, B.S.
Chemist

Submission #: 9707000010 lims

NOTE: Submitted material will be retained for 60 days unless notified or consumed in analysis. Material determined to be hazardous will be returned or a \$20 disposal fee will be assessed. Our letters and reports are for the exclusive use of the client to whom they are addressed. The use of our name must receive our prior written approval. Our letters and reports apply to the sample tested and/or inspected, and are not necessarily indicative of the qualities of apparently identical or similar materials.

Page 1 of 5

86969 to 86975